STROBRIDGE ELEMENTARY SCHOOL

ALAMEDA COUNTY UNINCORPORATED AREAS SAFE ROUTES TO SCHOOL PLAN

PROJECT OVERVIEW

Strobridge Elementary School is located in Hayward, California, and is part of the Hayward Unified School District. In 2016-17 there were 550 students enrolled at Strobridge Elementary School. An on-site walk audit was conducted on Wednesday afternoon, May 24th, 2017 with school administrator Wendy Sagi, Patrick Gilster (F&P), and Diwu Zhou (F&P).

ISSUES & CONCERNS

PRIORITY

1. Pedestrian circulation and safety
2. Visibility concerns on Riverbank Avenue where the roadway bends

GENERAL

1. Lack of curb ramps
2. Lack of bicycle facilities
3. Constrained walkway at internal bus pick-up/drop-off area.
4. Sidewalk gaps

COLLISION HISTORY

1. No pedestrian collisions reported
2. No bicycle collisions reported

PROJECT RECOMMENDATIONS

PRIORITY

P1 Crosswalk enhancements at the mid-block crosswalk on Bedford Drive.
Addresses Issue(s): Priority 1 & 2, General 1

P2 Parking restrictions and sidewalk repairs on Riverbank Avenue.
Addresses Issue(s): Priority 2, General 4

GENERAL

G1 Construct curb ramps on Grove Way from Oak Street to Tanglewood Drive, on Riverbank Avenue from the school to Kahlert Avenue, and along the easement from Kahlert Avenue to Tanglewood Drive.
Addresses Issue(s): Priority 1, General 1

G2 Intersection enhancements at the Bedford Drive/Grove Way intersection
Addresses Issue(s): Priority 1, General 1

G3 As an onsite improvement, widen constrained walkway at bus pick-up/drop-off
Addresses Issue(s): General 3

G4 As an onsite improvement, upgrade parking lot across the school.
Addresses Issue(s): Priority 1

G5 Construct sidewalks on Grove Way between Tanglewood Drive and Orange Avenue and between Foothill Boulevard and Oak Street.
Addresses Issue(s): General 4

KEY METRICS AT-A-GLANCE

17 (37) AM(PM) Peak Hour Pedestrians at Major Intersection Access

10 (8) AM(PM) Peak Hour Bicycles at Major Intersection Access

**Crossing Guard** Grove Way/Bedford Drive intersection

0 Pedestrian-involved collisions adjacent to school

0 Bicycle-involved collisions adjacent to school

Reported Collisions 2009-2014

STROBRIDGE ELEMENTARY SCHOOL

SAFE ROUTES TO SCHOOL
ALAMEDA COUNTY UNINCORPORATED AREAS

LEGEND

- **#** Priority Recomendation
- **#** General Recomendation
- ——— Sidewalk/Curb Extension
- ——— Red Curb
- ——— Sidewalk Repair
- School Crossing Assembly & Pedestrian Activated Warning Device
- Curb Ramp

G3

G1

Riverbank Ave

G4

Bedford Dr

P2

P1

G2

Grove Way

Grove Way

Gail Dr

Knoll Way

Shady Spring Rd

Tanglewood Dr

Lake Chabot Rd

Meg Ct

Baywood Ave

Hobert St

Tyee St

Quito Ct

Kahler Ave

Foothill Blvd

G5

G5

0'   100'   200'
Improvements not to scale

FEHR PEERS