

Castro Valley Elementary, Castro Valley

DRAFT

Safe Routes to Schools Improvement Plan

Site Assessment held May 2016



- 1 Anita Ave**
 - Install slotted speed cushions.
 - Install missing sidewalks.
- 2 San Miguel Ave**
 - Paint red curb at edges of Our Lady of Grace driveway to increase pedestrian visibility.
- 3 Anita Ave**
 - Install curb ramps.
 - Consider installing curb extensions.
 - Consider installing raised crosswalk.
 - Install pedestrian-scale lighting on path to school campus.
 - Trim vegetation encroaching on path.
- 4 North Parking Lot**
 - Install "Staff Parking Only" sign.
 - Install "No Drop-Off" sign.
 - Consider chaining or coning off driveway in the morning after staff have arrived.
- 5 San Miguel Ave**
 - Add diagonal down arrow to Rectangular Rapid Flashing Beacon (RRFB) assembly on west side of crosswalk.
 - Move beacon to be placed between signs to match typical RRFB configuration.
 - Install advance yield lines.
- 6 Anita Ave / Witcher St**
 - Install high visibility crosswalks.
- 7 Drop-off Zone**
 - Install "Pull Forward" sign at end of drop-off zone.
 - Replace existing cones with larger cones.
- 8 Anita Ave**
 - Install missing sidewalk and pedestrian facilities south to Castro Valley Blvd.
- 9 San Miguel Ave / Castro Valley Blvd**
 - Install Accessible Pedestrian Symbol (APS) push buttons at pedestrian crossings.