

Castro Valley Elementary, Castro Valley Safe Routes to Schools Site Assessment Recommendations

Site Assessment Held May 2016



- Anita Ave (Alameda County Public Works Agency (ACPWA))**
-Slotted speed cushions.
-Sidewalks where needed to close gaps (in design). In the short-term, consider striping white edge line to delineate pedestrian space.
- San Miguel Ave (ACPWA/Castro Valley Unified School District (CVUSD))**
-Red curb at edges of Our Lady of Grace driveway to increase pedestrian visibility.
- Anita Ave (ACPWA/CVUSD)**
-Curb ramps and curb extensions (in design).
-Raised midblock crosswalk (in design).
-Rapid Rectangular Flashing Beacons (RRFB) (in design).
-Pedestrian-scale lighting on path to school campus (CVUSD).
-Trimming vegetation that encroaches on path (CVUSD).
- North Parking Lot (CVUSD)**
-"Staff Parking Only" sign.
-"No Drop Off" sign.
-Closing off driveway in the morning after staff have arrived.
- San Miguel Ave (ACPWA)**
-Diagonal down arrow on RRFB assembly on west side of crosswalk.
-Beacon between signs to match typical RRFB configuration
-Advanced yield lines.
- Anita Ave/Witcher St (ACPWA)**
-High-visibility crosswalk.
- Drop-off Zone (CVUSD)**
-"Pull Forward" sign at end of drop-off zone.
-Larger cones to replace existing smaller ones.
- Anita Ave (ACPWA)**
-Missing sidewalk and pedestrian facilities south to Castro Valley Blvd (in design). In the short-term, consider striping white edge line to delineate pedestrian space.
The above items are recommendations only and based on Safe Routes to Schools site assessments best practices. Feasibility determination, final design, funding, and implementation of any recommended improvements is the responsibility of the appropriate governing agencies.